OGMCOAL - 0150032 East Mountain Inspection Reports

From:

Priscilla Burton

To:

Jay Marshall; OGMCOAL

Date:

9/7/2012 2:50 PM

Subject:

0150032 East Mountain Inspection Reports

Attachments:

0150032 Insp Rpt 3224 08312012.pdf; 0150032 Insp Rpt 3102 8242012.pdf; 0150032 Insp

Rpt 2905 10312011.pdf; 015032 Insp Rpt 2842 7212011.pdf; 0150032 Insp Rpt 2883

9292011.pdf

Hello Jay,

I've attached inspection reports for my site visits on 8/21/2012 and 8/31/2012. I am very impressed with the work of the SCAMP Excavation Crew. They have gotten a lot accomplished under difficult working conditions of at high altitude, long hiking/hauling distances, and after frequent rains, treacherous driving conditions.

I am also sending the inspection reports from the three site visits I made last year (#2842, #2883 and #2905), describing the first inspection of the slide area and installation of excelsior logs on the head cut and reclamation progress on the road.

Priscilla

Priscilla Burton

Priscilla Burton, CPSSc Sr. Environmental Scientist Utah Division of Oil Gas & Mining 319 No. Carbonville Rd, Ste.210 Price UT 84501 (435) 613-3733



GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
OGM	Priscilla Burton
Company	Jay Marshall
Other	Jerry Cripps

Inspection Report

Permit Number:	C0150032
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, August 28, 2012
Start Date/Time:	8/28/2012
End Date/Time:	8/31/2012
Last Inspection:	Friday, August 24, 2012

Inspector: Priscilla Burton, Weather: cloudy, rain

InspectionID Report Number: 3224

Accepted by: jhelfric 9/6/2012

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

6,235.80	Total Permitted
27.15	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

Types of Operations Underground

✓ Federal ☐ State Surface County Loadout Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Met at the site at the beginning of the week with Jay Marshall (UEI) and Jerry Crieps (Scamp Excavation) to layout placement of excelsior logs and get crews started. Met Jerry Crieps at the site at the end of the week (Friday) to observe progress of crews on the installation of the logs. Crews had hauled 29 excelsior logs down to the slide area and installed them in 9 rows. Three more logs will be hauled down to the site to complete the rows next week. See photos in the image folder dated 8/31/2012.

Inspector's Signature:

Date

Friday, Augus

Inspector ID Number: 37

Inspection Date: Tuesday, August 28, 2012

Page 2 of 3

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet


Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Tuesday, August 28, 2012

Page 3 of 3

10. Slides and Other Damage

Crews had hauled in 29, ten foot excelsior logs to the slide location, a distance of approximately 3/4 mile from the East Mountain saddle. A game trail provided the easiest access for the foot traffic. The logs were set in 9 rows approximately 15 feet apart on the contour. Some, but not all of the logs were staked. The remaining logs will be staked next week. Work will resume on Tuesday after the Labor Day holiday. We discussed seeding rates and the seed mix and the remainder of the work to be done.





DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER **Executive Director**

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representativ	es Present During the Inspection:
OGM	Priscilla Burton

Inspection Report

Permit Number:	C0150032
Inspection Type:	TECHNICAL
Inspection Date:	Friday, August 24, 2012
Start Date/Time:	8/24/2012 9:30:00 AM
End Date/Time:	8/24/2012 3:00:00 PM
Last Inspection:	Tuesday, August 21, 2012

Inspector: Priscilla Burton,

Weather: sun 60

InspectionID Report Number: 3210

Reprocessing

Accepted by: jhelfric 9/6/2012

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

Other

County: EMERY

Phase III

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership	Types of Operations		
6,235.80 Total Permitted	✓ Federal	✓ Underground		
27.15 Total Disturbed	State	Surface		
Phase I	☐ County	Loadout		
Phase II	Fee	Processing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Flagged the game trail that will be improved to be the connecting link for USFS trail 085 on East Mountain.

Inspector's Signature:

Inspector ID Number: 37

Date

Monday, Augu



Note 59 Th West Plant the Division of Oil, Gas and Mining. telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Inspection Date: Friday, August 24, 2012

Page 2 of 3

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.

 b. For PARTIAL inspections check only the elements evaluated.

 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities	✓		✓	
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0150032 Inspection Type: TECHNICAL

Inspection Date: Friday, August 24, 2012

Page 3 of 3

17. Other Transportation Facilities

Flagged a trail across the west side of East Mountain to be improved for foot and horse traffic. Crews will need a chain saw to cleared a few downed logs; a hand saw or clippers to remove low hanging pine branches, and shovels to define the trail in a couple of locations. I asked Kyle Beagley if he and Bill Broadbear would walk the flagged trail and make modifications where they see fit, this week, before the reclamation crew arrives at the site.



DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Representativ	es Present During the Inspection:
OGM	Priscilla Burton
Company	Dave Shaver

Inspection Report

Permit Number:	C0150032
Inspection Type:	PARTIAL
Inspection Date:	Thursday, October 20, 2011
Start Date/Time:	10/20/2011 10:00:00 AM
End Date/Time:	10/31/2011 2:00:00 PM
Last Inspection:	Tuesday, October 11, 2011

Inspector: Priscilla Burton,

Weather: sunshine turning to overcast and snow flurries

InspectionID Report Number: 2905

Accepted by: jhelfric 11/1/2011

Permitee: GENWAL RESOURCES INC
Operator: GENWAL RESOURCES INC
Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership	Types of Operations		
6,235.80 Total Permitted	✓ Federal	✓ Underground		
27.15 Total Disturbed	☐ State	Surface		
Phase I	☐ County	Loadout		
Phase II	☐ Fee	Processing		
Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The site has dried out from previous rains and SCAMP returned to the site on October 20, 2011. By Tuesday October 25 the SITLA road was recliaimed to within 700 ft. of the USFS boundary. Wood straw had been spread to the point of the ridge, approximately 1,000 feet west. No seed has been spread yet. More laborers are needed to complete this job before the weather shuts it down. Refer to photos in the Images folder taken in October 2011.

Inspector's Signature:

Date

Saturday, Octo



Inspection Date: Thursday, October 20, 2011

Page 2 of 3

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.

 b. For PARTIAL inspections check only the elements evaluated.

 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	~		✓	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.1	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit	1			
21.	Bonding and Insurance				
22	Other				

Inspection Date: Thursday, October 20, 2011

Page 3 of 3

4.c Hydrologic Balance: Other Sediment Control Measures

I recommended that the six remaining (new) excelsior logs be installed at the location of the former French drain along the SITLA road, because the reclaimed slope is steep in this location and it meets an equally steep undisturbed slope with no concave area or vegetation to slow flow.

12. Backfilling And Grading

Chase Webster, SCAMP hoe operator worked Oct 20 through Saturday Oct. 22 and Monday Oct 24. At midday on Tuesday, October 25, the SITLA road was reclaimed to approximately 700 ft from the USFS boundary.



DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representatives Present During the Inspection:			
OGM	Priscilla Burton		
Company	Dave Shaver		

Inspection Report

Permit Number:	C0150032
Inspection Type:	TECHNICAL
Inspection Date:	Wednesday, August 17, 2011
Start Date/Time:	8/17/2011 9:30:00 AM
End Date/Time:	8/17/2011 3:30:00 PM
Last Inspection:	Thursday, July 21, 2011

Inspector: Priscilla Burton,

Weather: sun 70F

InspectionID Report Number: 2842

Accepted by: jhelfric 9/14/2011

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

6,235.80	Total Permitted	
27.15	Total Disturbed	
	Phase I	
	Phase II	
	Phase III	

Mineral Ownership **Types of Operations**

✓ Underground ✓ Federal Surface State Loadout County Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Investigated a report of a slide in the reclaimed East Mountain area. Found a failure approximately 15 ft. X 30 ft. in the vicinity of the "oops" road shown on Figure 4 of Appendix 22A. The mass of saturated soil had slid to the bottom of the slope, a distance of approximately 150 ft., pushing topsoil to the side, creating berms on either side of the slide area.

Inspector's Signature:

Date

Tuesday, Augu



Inspection Date: Wednesday, August 17, 2011

Page 2 of 3

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
<u></u> 21.	Bonding and Insurance				
	Other				

Inspection Date: Wednesday, August 17, 2011

Page 3 of 3

10. Slides and Other Damage

Photos of the area that slid at East Mountain are in the images folder dated 8/17/2011. The area was on the reclaimed "oops" road, not part of the pads that were reclaimed, but just below pad 6 (see Figure 4, App. 22A). The area of failure left a cut approximately 15 ft. high and 30 ft. wide. The supersaturated soil slid over the hill, pushing topsoil to the side and leaving a trail that is approximately 150 ft. long on a very steep (28%) slope. The saturated soil slid over native ground and vegetation can be seen growing in the center of the slide area and in the topsoil "berms" that were pushed to the side.

I recommend stabilizing the area with rake and seed. Installation of excelsior logs may be helpful, but would be difficult to bring to the site. (In another location, photographs attached below, the excelsior logs did maintain the slope against a slide and prevented wholesale failure.) I do not recommend bringing in equipment to repair the damage, as this would disturb more ground to gain access.



DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Priscilla Burton

Inspection Report

Permit Number:	C0150032
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, September 20, 2011
Start Date/Time:	9/20/2011 12:00:00 PM
End Date/Time:	9/29/2011 3:30:00 PM
Last Inspection:	Wednesday, September 14, 2011

Inspector: Priscilla Burton,

Weather: sun, 70 F

InspectionID Report Number: 2883

Accepted by: jhelfric 10/6/2011

Permitee: GENWAL RESOURCES INC
Operator: GENWAL RESOURCES INC
Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership	Types of Operations		
6,235.80 Total Permitted	✓ Federal	✓ Underground		
27.15 Total Disturbed	State	Surface		
Phase I	☐ County	Loadout		
Phase II	☐ Fee	Processing		
Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

SCAMP Excavation installed excelsior logs on the slide area below pad 6 and has begun work on reclamation of the SITLA access road. SCAMP crew includes Josh LeBond, foreman; John Dow, equipment operator, and two laborers. Seth Wallace, USFS Road Engineer, was present on Thursday September 29, 2011. Photographs are in the Image folder for the mine.

Inspector's Signature:

Date

Friday, Septemb



Inspection Date: Tuesday, September 20, 2011

Page 2 of 4

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
- a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues	V		✓	
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	✓		V	
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Date: Tuesday, September 20, 2011

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

MRP Appendix 5-22A is the reclamation plan for the East Mountain Emergency Drill Pads and Access Roads. Reclamation of the remaining area SITLA road is described in item 3 on pg. 10 and reclamation of the remaining USFS road is described in item 4 on pg. 13. According to Attachment #2, the SITLA segment is 4,959 ft. long and the USFS segment is 2,573 ft. long. Attachment #4 shows the location of the pads and the "oops" road.

Attachment 12 is the Special Use permit for the access road. This permit requires a two foot trail be re-established. This was confirmed by Seth Wallace.

9. Protection of Fish, Wildlife and Related Environmental Issues

I walked the site from pads 5 down to pad 3 and removed a sack of thistle seed and hounds tongue and destroyed thistle rosettes.

10. Slides and Other Damage

A slope failure occurred on SITLA land, just below pad 6 this spring. The slide crossed the oops road and the access road below. A three man crew carried in 18 excelsior logs (approximately 1/3 mile down a steep slope) and installed three rows of 6 logs above the head of the slide. The logs were trenched in and staked. The slide area is vegetated with wild rose and snowberry shrubs. The toe of the slide is adjacent to a running seep that emanates up slope, east of the slide. The slide appears to be greater than 200 ft. in length. In the center of the slide there is a wedge of soil approximately 4 ft. deep and 20 ft. wide and 25 ft. long that will continue to move downward.

Inspection Date: Tuesday, September 20, 2011

Page 4 of 4

12. Backfilling And Grading

SCAMP has a Komatsu PC 300 LC trackhoe with a 2 yd bucket, a CAT D6N XL dozer with 2 ft. ripper shanks, and a sheeps foot roller on site.

Straw bales (500 lbs) were placed every 100 ft. or alternatively 9, 50 lb bales were placed every 15 feet along the USFS access road and for the first 0.5 miles of the SITLA road. Bales did not extend all the way to the far north end of the SITLA access road. The crew later hauled more bales in for the full length of the SITLA road.

Aproximately 400 ft of SITLA road at the north end has been pocked with a track Komatsu PC 300 LC (approximately 2 yd bucket). Work around the bend to the south requires pulling up the outslope of the road, but the reclamation appeared to be extending beyond the outslope to undisturbed area. Mr. Shaver of UEI was unavailable, so this was brought to Shane Campbell's attention.

A discussion the Seth Wallace concerning the location of the trail took place. Questions as to where the reclaimed trail should meet up with the existing trail remain. Mr. Wallace requested removal of the red gate and placement of boulders to prevent access. A question remained as to whether the parking area in front of the red gate should be ripped and seeded.

13. Revegetation

Emerging blades of grass testify to the recent seeding of the slide area, however the grass was only in one location and otherwise there was little evidence of seeding. Since equipment access is impossible, excess seed should be applied to the slide area to try and stabilize it. The final seed mix is listed in Attachment 7. It includes Triticale, which may help to stabilize this slide.

16.b Roads: Drainage Controls

Excelsior logs are being removed as reclamation progresses. Excelsior matting is being scattered over pocked ground. Netting is being removed.

SCAMP crew was unaware of existing French drains. Plans are to install new French drains in the same location(s).

Seth requested the dips and excelsior logs in the existing roadway be replaced in the foot path.